(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING HAL060109 05/06/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 8700 LAYWERS ROAD THE LITTLE FLOWER ASSISTED LIVING RESII CHARLOTTE, NC 28227 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report of Biennial Construction Survey by Dennis Harrell and Ed Miller on 5-6-2015. Records indicate this facility was first licensed or submitted for licensure on or about 8-16-1996, for 49 beds. Based on the this information, the facility is required to meet the 1996 Rules for the Licensing of Adult Care Homes (Homes for the Aged and Family Care Homes); the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds; and the 1996 North Carolina State Building Code Section 409.1-Group I. C 101 Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm". copies of which are available at the Division of Health Service Regulation, 701 Barbour Drive, Raleigh, North Carolina, 27603 at no cost; This Rule is not met as evidenced by: Based on observation, corridor doors did not positively latch closed as required by Section Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

	NT OF DEFICIENCIES I OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDING: (X2)	CONSTRUCTION D1	(X3) DATE SURVEY COMPLETED
		HAL060109	B. WING		05/06/2015
	PROVIDER OR SUPPLIER TLE FLOWER ASSIST	'ED LIVING RESII 8700 LA'	DDRESS, CITY, ST YWERS ROAD DTTE, NC 2822		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIC (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROF DEFICIENCY)	D BE COMPLE
C 101	latch cannot resist the Findings include; The double doors for	ge 1 doors that do not positively the passage of smoke. rom the corridor to the Dining ipped with latching hardware.	C 101		
C 166	SECTION .0300 - F 10A NCAC 13F .03 FURNISHINGS (a) Adult care home (5) be maintained i orderly manner, fre hazards;	06 HOUSEKEEPING AND	C 166		
	Based on observovers had been repainting. The room unlocked potentially exposed energized Based on observomen's bathroom	vation, the toilet in the near the nurse station was the floor. Loose toilets can			
C 189	SECTION .0300 - F 10A NCAC 13F .03 REQUIREMENTS (a) The building an mechanical, and plu	11 OTHER Ind all fire safety, electrical, umbing equipment in an adult maintained in a safe and	C 189		

Division of Health Service Regulation

STATE FORM 6899 76N421 If continuation sheet 2 of 11

Division	of Health Service Re	egulation				
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		, ,	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		SURVEY LETED	
		HAL060109	B. WING		05/0	6/2015
NAME OF I	PROVIDER OR SUPPLIER	STREET A	DDRESS, CITY, S	STATE, ZIP CODE		
8700 I AY			YWERS ROAI			
THE LIT	TLE FLOWER ASSIST	FD LIVING RESII	OTTE, NC 282			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOU! CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETE DATE
C 189	Continued From pa	ige 2	C 189			
	facilities with the ex	apply to new and existing acception of Paragraph (e) ly to existing facilities.				
	fire rated walls and, in several locations are not sealed with one-hour fire rated missing ceiling radi possibility that a fire quickly spread to of Findings include: a. Unsealed conduceiling of the Busine b. Hole by the exit near room 30, c. Unsealed conduin the attic on the w.d. Hole in ceiling in on the west side, e. Holes around pig suppression system	vation the required one-hour /or ceilings were compromise. Holes and penetrations that materials approved for use in construction and inoperable of ation dampers present the exthat begins in one space carther areas of the facility. Let sleeves (2) through the less office, light in the corridor ceiling with sleeve in the furnace room west side, in the furnace room in the atticulation.	or			
	room, g. Holes in the wal laundry,	I in the soiled utility off the				
	furnace room on th i. Large holes and combustion air inlet the east side,	gaps around the Hi-Lo ts in the attic furnace room on				
	corners of the attic k. Gypsum comporwalls of the attic fur	sum compound and tape in the furnace room on the east side und and tape falling off the race room on the east side, at the wall of the attic furnace.				

room on the east side,

Division of Health Service Regulation								
	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIDENTIFICATION N		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED		
		HAL060109		B. WING		05/0	6/2015	
NAME OF F	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE			
THE LITT	TLE FLOWER ASSIST	ED LIVING RESII		WERS ROAL				
T				TTE, NC 282				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCE MUST BE PRECEDED B SC IDENTIFYING INFORN	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROINT DEFICIENCY)	D BE	(X5) COMPLETE DATE	
C 189	Continued From pa	ge 3		C 189				
C 189	m. Holes in the wa furnace room on the n. Unsealed sleeved o. Holes in ceiling obasement, p. Cracks where the water heater room of q. Unsealed sleeved barrier wall, r. Residential fire for around the sprinkle penetrating the attice Residential fire foar Institutional Occupates. One of the fire dependent of the side was propped of the are held open with manufacturer's approperly in the event. The sprinkler escentially fitted to the comproduction in the folionic. Closet off room ii. Closet off room iii. Closet off laundiv. Laundry. 2. Based on observance when the activation of the firefailed to latch close do not close complete possibility that a fireful quickly spread to the second of the seco	Il of the stairway to e east side, es (2) in the basement of water heater roome wall meets the confit the basement, es (3) through the account was down used to seal of r line and at flanges as smoke barrier wall m is not approved francies. ampers in the HVA attic furnace room of the pen with wood. Dameans other than a roved fuse link will not of a fire. Cutcheon was missicalling complete the lowing locations; 26, nom 16, ry, vation, the cross-consistency was are equipped with the doors were closes are equipped with the doors were closes alarm system both d. Cross-corridor of the etely and latch present that begins in one that the existing the wation, the motorized wation wation, the motorized wation, the motorized wation, the motorized wation wation wation wation.	ent ceiling, m off the eiling in the eiling in the eiling in the ttic smoke penings at ducts l. or use in C duct on the east ampers that ent close one-hour eilitching ed by a doors loors that ent the space can facility.	C 189				
	Based on observand fire damper pro through the attic sm	tecting the duct pe	netration					

Division of Health Service Regulation						
	IT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPL	E CONSTRUCTION	(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER:	A. BUILDING: 01		COMPLETED	
			1			
		HAL060109	B. WING		05/0	6/2015
		HALUGUIU9			05/0	0/2015
NAME OF I	PROVIDER OR SUPPLIER	STREET AL	DRESS, CITY, S	STATE, ZIP CODE		
		8700 LAY	WERS ROAL)		
THE LIT	TLE FLOWER ASSIST	CHARLO	TTE, NC 282	227		
(X4) ID	SUMMARY STA	ATEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF CORRECTION	ON	(X5)
PREFIX		Y MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOUL		COMPLETE
TAG	REGULATORY OR L	SC IDENTIFYING INFORMATION)	TAG	CROSS-REFERENCED TO THE APPROI	PRIATE	DATE
				DEFICIENCY)		
C 189	Continued From pa	nge 4	C 189			
	Smoke dampers th	at do not work as designed				
		oke generated from a fire on				
		oke barrier wall from traveling				
		on the other side of the wall.				
	4 Rased on obser	vation, the corridor door to the				
		s held open by a mechanical				
		evented from closing quickly				
		st the passage of fire and				
		oors that do not close				
		ch present the possibility that a				
		ne space can quickly spread				
		the remainder of the facility.				
		vation, one of the fire rated				
		om the furnace room on the				
		t latch. A fire door that does				
		w a fire in the furnace room to				
		attic and other areas of the				
	facility.					
	, , ,					
	6. Based on obser	vation, the kitchen door was				
	prevented from late	ching as required to be				
		sage of smoke. An improperly	,			
		or could allow smoke from a				
	fire in the kitchen to	travel quickly to the dining				
		mainder of the facility.				
	Findings include;					
		rdware had been removed				
	from the kitchen door.					
		had been removed from the				
	kitchen door frame.					
	c. The kitchen doo	r was tied open.				
	7 Rased on obser	vation, the exterior dryer vents				
		led with lint. Clogged dryer				
		rerheating and a fire.				
	Torrico our oudge ov	omoding and a mo.				
	8. Based on Obser	rvation, the building was not				
		e manner by not properly				

6899

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 (X3) DATE S COMPL				
		HAL060109	B. WING		05/0	6/2015
	PROVIDER OR SUPPLIER	FD LIVING RESII 8700 LAY	DRESS, CITY, S WERS ROAL TTE, NC 282			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	D BE	(X5) COMPLETE DATE
C 189	could affect all resic cylinders fall, break cylinder and turning Findings include: Several portable me stored in an unapproper of the stored in t	nedical oxygen cylinders. This dents, staff and visitors if ing their valves, propelling the it into a dangerous projectile. edical oxygen cylinders were eved milk crate in room 24. evation, there were openings in here circuit breakers had been in electrical panels expose to energized electrical eas missing in the electrical eas missing in the electrical	C 189			
C 193	SECTION .0300 - F 10A NCAC 13F .03 REQUIREMENTS (4) Ovens, ranges resident activity or r used except under degree of staff supe facility's assessmer resident. The opera		C 193			

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING _ HAL060109 05/06/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 8700 LAYWERS ROAD THE LITTLE FLOWER ASSISTED LIVING RESII CHARLOTTE, NC 28227 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 193 Continued From page 6 C 193 (5) Ovens, ranges and cook tops located in resident rooms shall have a locking feature provided, controlled by staff, to limit the use of the equipment by residents who have been assessed by the facility to be incapable of operating the equipment in a safe manner. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: Based on observation, the electrical disconnect provided at the range in the activity room was just a circuit breaker with no locking feature. Failure to lock the range in the off position could allow residents to use the range without supervision and to be injured. C 199 Exhaust Ventilation C 199 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by:

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED		
		HAL060109	B. WING		05/0	6/2015
NAME OF F	PROVIDER OR SUPPLIER	STREET AD	DRESS, CITY, S	STATE, ZIP CODE		
THE LITTLE FLOWER ASSISTED LIVING RESIL			WERS ROAD TTE, NC 282			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	D BE	(X5) COMPLETE DATE
C 199	Continued From pa	ge 7	C 199			
	maintain required en Non-functioning extunhealthy build-up bacteria. Findings include; a. The exhaust system off room 21. b. The exhaust system off room 24. c. The exhaust system off room 24. d. The exhaust system of the	stem was not working at the				
C 123	5. The requirement rooms are: e. The bathrooms designed to provide toilet rooms with two (commodes) shall he curtains for each we shower shall have put this Rule is not me Based on observation provided at the tub The room also has to provide curtains	and toilet rooms must be privacy. Bathrooms and toilet or more water closets nave privacy partitions or ater closet. Each tub or privacy partitions or curtains.	C 123			

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING _ HAL060109 05/06/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 8700 LAYWERS ROAD THE LITTLE FLOWER ASSISTED LIVING RESII CHARLOTTE, NC 28227 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 124 Continued From page 8 C 124 C 124 C 124 Bathrooms-Hand Grips IV. The Building C. Physical Environment (10 NCAC 42D .1503) 5. The requirements for bathrooms and toilet f. Hand grips must be installed at all commodes, tubs and showers used by or accessible to residents. This Rule is not met as evidenced by: Based on observation, the hand grip provided was loosely mounted to the wall at the toilet in the central bath on the west side. Loose hand grips could cause a resident to fall. C 150 Exit Door Locks-Single Hand Motion C 150 IV. The Building C. Physical Environment (10 NCAC 42D .1503) 8. The requirements for outside entrances and c. All exit doors locks must be easily operable, by a single hand motion, from the inside at all times without keys. (This limits each door, to one locking device which meets the criteria set forth in this standard.) This Rule is not met as evidenced by: Based on observation, several exit doors require 2 hand motions to operate. Findings include: a. The required exit from the dining room is equipped with a door knob lock and a dead bolt. b. The front door exit requires 2 hand motions to open. c. The exit at room 8 requires 2 hand motions to open.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01			(X3) DATE SURVEY COMPLETED		
		HAL060109		B. WING		05/0	06/2015
	NAME OF PROVIDER OR SUPPLIER THE LITTLE FLOWER ASSISTED LIVING RESII CHARLO						
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY F SC IDENTIFYING INFORMAT	ULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPR DEFICIENCY)	ULD BE	(X5) COMPLETE DATE
C 157	Continued From pa	ge 9		C 157			
C 157	Outside Premises-0	Clean, Safe		C 157			
	13. The requireme a. The outside grouclean and safe cond This Rule is not me Based on observati approximately 5 inc sidewalk at the rear		trench, es of the				
C 173	Fire Extinguishers			C 173			
	.1601 through .1604 3. Fire extinguisher a. At least one 5 por ABC " type fire exti 2,500 square feet or b. One 5 pound or or CO2 type is require applicable, in the m This Rule is not me Based on observati	rs: Dund or larger (net changuisher is required for floor area or fraction larger (net charge) " Dired in the kitchen and aintenance shop.	arge) " or each i thereof. ABC " d, where				
	side needs recharg	ing. Improperly charg	ged fire				
C 175	Fire Safety-Evacuar IV. The Building E. Fire Safety Require. 1601 through .1604	uirements (10 NCAC	42D	C 175			

6899

STATEMENT OF DEFICIENCIES (X1 AND PLAN OF CORRECTION	1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01	ISTRUCTION (X3) DATE SURVEY COMPLETED	
<u> </u>	HAL060109	B. WING		05/0	6/2015
NAME OF PROVIDER OR SUPPLIER			STATE, ZIP CODE		
THE LITTLE FLOWER ASSISTED) I IVING RESII	WERS ROAD TE, NC 282			
PREFIX (EACH DEFICIENCY MU	MENT OF DEFICIENCIES UST BE PRECEDED BY FULL IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETE DATE
C 175 Continued From page	10	C 175			
6. A written fire/disasted diagrammed drawing) the local fire departme large print and posted each floor. This plan resident on admission orientation for all new some the company of the	ter plan (including a which has the approval of ent must be prepared in in a central location on must be reviewed with each and must be a part of the staff. as evidenced by: , the evacuation plan Hall was oriented wrong in	C 175			

Division of Health Service Regulation STATE FORM

76N421